| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|------------------------|------------------|
| DATE: | 8130104 - 9/7/04 | |
| GRID: | # 3A | |
| # OF DRUMS REMOVED: | 1210 | |
| DEBRIS: | Misc, Mital Tines - 74 | |
| DEPTH OF SAND: | 20'-22' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| | | |
| COORDINATES: | Northing | <u>Easting</u> |
| | 4836900 | MANANO |
| | 4336820 | 711435 |
| | 4336800 | 711435 711435 |
| SIZE OF EXCAVATION: | 45 x 60 x 22' | |
| ADDITIONAL COMMENTS: | | |
| | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|--|--|
| DATE: | 8/19/04 | |
| GRID: | 13A | |
| # OF DRUMS REMOVED: | 17 | |
| DEBRIS: | CAR MOTOR AND PRATS, MISC. METALS STEEL CABLE TIRES - 14 | |
| DEPTH OF SAND: | 25' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated material | |
| COORDINATES: | Northing | Easting |
| | 4336945 4336945 4336945 4336940 | 711425 - NE 711435 - SW 711425 - SE 711425 SV |
| SIZE OF EXCAVATION: | 40 X38 X25 | |
| ADDITIONAL COMMENTS: | Escaration increased from original marking due to cave-ins. | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|--------------------|------------|
| DATE: | 8/17/04 | |
| GRID: | 30C | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Misc. MeTal | |
| DEPTH OF SAND: | 14 | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated material | |
| | | |
| COORDINATES: | <u>Northing</u> | Easting |
| | 4336960 -N | 711360 - € |
| | | |
| SIZE OF EXCAVATION: | 6 x 21 x 14 | |
| ADDITIONAL COMMENTS: | | |
| | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|-----------------|----------------|
| DATE: | 8116104 | |
| GRID: | 3.0B | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Misc. debris | |
| DEPTH OF SAND: | 18 | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| | | |
| COORDINATES: | Northing | <u>Easting</u> |
| , | 4336955-N | 711370 E |
| | | |
| SIZE OF EXCAVATION: | 5 × 10 × 18 | |
| ADDITIONAL COMMENTS: | | |
| |) | |

| GRI | HERRON AVENUE SITE D EXCAVATION SUMMA | ARY |
|-------------------------|---------------------------------------|----------------|
| DATE: | 8/ /6/04 | ; |
| GRID: | 30 A | |
| # OF DRUMS REMOVED: | 2 | |
| DEBRIS: | Mirc Debris | |
| DEPTH OF SAND: | 15' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | | |
| | Excavated mater | iai |
| COORDINATES: | Northing | <u>Easting</u> |
| | 4336945 - N | 711365 - E |
| SIZE OF EXCAVATION: | 4'x10'x15' | |
| | TXIOXIS | |
| ADDITIONAL COMMENTS: | 4×10×15 | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|-----------------|----------|
| DATE: | 81 16104 | |
| GRID: | 2913 | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | MISC. WETAI | |
| DEPTH OF SAND: | 15' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | Northing | Easting |
| | 4336940 - N | 711375-E |
| | | |
| SIZE OF EXCAVATION: | 4'x 10'x 15' | |
| ADDITIONAL COMMENTS: | | |
| | | |

| | HERRON AVENUE SITE D EXCAVATION SUMMA | |
|----------------------|--|-------------------------------|
| DATE: | 8//6/04 | |
| GRID: | 29 A | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | 1-Beer Keg, misc. metal | |
| DEPTH OF SAND: | 15' | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | |
| COORDINATES: | Northing 4336935 - N 4336930 - S | Easting 711370 - N 711370 - S |
| SIZE OF EXCAVATION: | 3 40 x 15' | |
| ADDITIONAL COMMENTS: | | |

| GRI | HERRON AVENUE SITE D EXCAVATION SUMMA | |
|-------------------------|--|---|
| DATE: | 8//7/04 | |
| GRID: | 9A | |
| # OF DRUMS REMOVED: | 158 | |
| DEBRIS: | Misc. Metal Tines= 42 | |
| DEPTH OF SAND: | 25' | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | |
| COORDINATES: | Northing 4336880 4336880 4336880 4336870 4336870 | Easting 111 425 -E 111435 111425 711435 |
| SIZE OF EXCAVATION: | 36'x37'x25' | |
| ADDITIONAL COMMENTS: | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|--|------------------------------|
| DATE: | 8/18/04 | |
| GRID: | 10 A | |
| # OF DRUMS REMOVED: | 102 | |
| DEBRIS: | MISC WETAL, WATER HEATER TINES = 16 | |
| DEPTH OF SAND: | 25' | |
| PHOTOS: | Sidewall | |
| L. | Bottom of grid | |
| | Excavated material | |
| COORDINATES: | Northing 4336880 4336880 4336898 4336898 | Easting 111425 711425 711435 |
| SIZE OF EXCAVATION: | 36'x 46'x 27' | |
| ADDITIONAL COMMENTS: | HIT GIOLNA WATE | en at 25' |

| GR | HERRON AVENUE SITE | |
|-------------------------|---------------------------|-----------|
| DATE: | 8/23/04 | |
| GRID: | #13B | |
| # OF DRUMS REMOVED: | | |
| DEBRIS: | Misc. MeTal Tires - 36 | |
| DEPTH OF SAND: | 78 | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated material | |
| COORDINATES: | Northing | Easting |
| | 433 CAST 5 | 711430 -N |
| | 4336950 | 711430 -8 |
| SIZE OF EXCAVATION: | 30'x30'x28' | |
| ADDITIONAL COMMENTS: | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|--|------------------|
| DATE: | 8/33 /04 | |
| GRID: | #1800 13C | |
| # OF DRUMS REMOVED; | 3 | |
| DEBRIS: | Misc, MeTal Tirês - 16 | |
| DEPTH OF SAND: | 15' | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | |
| COORDINATES: | Northing 4336950 | Easting 711-12-3 |
| SIZE OF EXCAVATION: | 11 × 18' × 15-' | |
| ADDITIONAL COMMENTS: | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|----------------------------|---------|
| DATE: | 8123104 | |
| GRID: | #12A | , |
| # OF DRUMS REMOVED: | / | |
| DEBRIS: | Misc. MaTal CA. TinES-3 | n Hood |
| DEPTH OF SAND: | 17 | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | Northing | Easting |
| | 4336925 | 711418 |
| SIZE OF EXCAVATION: | 10'x20'x17' | : |
| ADDITIONAL COMMENTS: | | |
| | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|-------------------|---|
| DATE: | 81 104 | |
| GRID: | CeA | |
| # OF DRUMS REMOVED: | 18 | |
| DEBRIS: | Misc. MeTal, Cank | 000 |
| DEPTH OF SAND: | 20' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | | 3-1 |
| | Excavated mater | ıaı |
| COORDINATES: | Northing | <u>Easting</u> |
| | 4336955 | TN435 -NW |
| | 4336755 | 711445 - NE |
| | 4336940 | 711435 -NW 711445 - NE 7118435 - SW 711445 -SE |
| SIZE OF EXCAVATION: | 45 × 33 × 20 | |
| ADDITIONAL COMMENTS: | | |
| | | |

| | HERRON AVENUE SITE D EXCAVATION SUMMA | ARY |
|----------------------|---------------------------------------|----------------|
| DATE: | 8 <i>l231</i> 04 | : |
| GRID: | #4A | ` |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Misc. Matal Tines - 0 | |
| DEPTH OF SAND: | 22' | • |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | Northing | <u>Easting</u> |
| , , , | 4336915 | 711440 |
| SIZE OF EXCAVATION: | 12'X 15'X 22' | |
| ADDITIONAL COMMENTS: | | |
| | , | |

| GR | HERRON AVENUE SITE ID EXCAVATION SUMM | | |
|-------------------------|---------------------------------------|---------------------------------------|--|
| DATE: | 8/36/04 | | |
| GRID: | #5A | | |
| # OF DRUMS REMOVED: | J | | |
| DEBRIS: | Large Metal Box, Tines-le | Large Metal Box, Misc. METAL Tikes-6 | |
| DEPTH OF SAND: | 12' | | |
| PHOTOS: | Sidewall | | |
| | Bottom of grid | | |
| | Excavated material | | |
| COORDINATES: | Northing | Easting | |
| | 4336940 | 711435 | |
| | 4336930 | 711435 | |
| SIZE OF EXCAVATION: | 25 X 28 X 22' | | |
| ADDITIONAL COMMENTS: | | | |
| | | | |

| GRI | HERRON AVENUE SITE D EXCAVATION SUMMA | ARY |
|-------------------------|---------------------------------------|----------------|
| DATE: | 8JH04 | |
| GRID: | #2A | |
| # OF DRUMS REMOVED: | 64 | |
| DEBRIS: | CAR PARTS, MISC. Mel TINES-19 | ta / |
| DEPTH OF SAND: | 20' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | rial |
| COORDINATES: | Northing 4336880 | <u>Easting</u> |
| | 4336870 | |
| SIZE OF EXCAVATION: | 40'x40'x20' | |
| ADDITIONAL COMMENTS: | | |
| | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|-------------------|----------------|
| DATE: | 912\104 | |
| GRID: | lhob 15B | |
| # OF DRUMS REMOVED: | Ø | |
| DEBRIS: | Rebar | |
| DEPTH OF SAND: | 6' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| | Excavated Mater | iai |
| COORDINATES: | <u>Northing</u> | <u>Easting</u> |
| | 4336860 | 711411 |
| | • | |
| SIZE OF EXCAVATION: | 3×u×レ′ | , |
| ADDITIONAL COMMENTS: | RAN iNTO MAN HOLE | at 61 |
| | | |

.

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|----------------------------------|----------------|
| DATE: | 9/2 / 104 | |
| GRID: | #1A | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Guand Pail, Misc, W Tines - 1 | ٠٠ اس (|
| DEPTH OF SAND: | 15 | |
| PHOTOS: | Sidewall | ***** |
| | Bottom of grid | |
| | Excavated mater | ial |
| | | |
| COORDINATES: | <u>Northing</u> | <u>Easting</u> |
| | 4.33687 | 711439 |
| | | |
| SIZE OF EXCAVATION: | 4.410.415 | |
| ADDITIONAL COMMENTS: | | |
| | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | \RY |
|--|---------------------|----------------|
| DATE: | 9/2//04 | |
| GRID: | #18 | |
| # OF DRUMS REMOVED: | O | |
| DEBRIS: | Rebar, Wisc, Mata | / |
| DEPTH OF SAND: | 20 ' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | Northing 4336851 | Easting 711436 |
| SIZE OF EXCAVATION: | 4 × 10 × 20 | |
| ADDITIONAL COMMENTS: | | |
| Í | | |

.

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|-----------------------------------|---------------|
| DATE: | 9/8/04 - 9/23/04 | |
| GRID: | 48 | |
| # OF DRUMS REMOVED: | 705 | |
| DEBRIS: | misc. METAL, Reconstruction Debri | base Concrete |
| DEPTH OF SAND: | 70 | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | rial |
| COORDINATES: | Northing | Easting |
| SIZE OF EXCAVATION: | 40 x 35 zo' | |
| ADDITIONAL COMMENTS: | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|---|---------|
| DATE: | 9/24/04 | |
| GRID: | 113 | |
| # OF DRUMS REMOVED: | 727 drums | |
| DEBRIS: | Misc. Mutal, Ruban Tines - 36 | |
| DEPTH OF SAND: | 25' | |
| PHOTOS: | Sidewall Bottom of grid Excavated materia | al |
| COORDINATES: | Northing | Easting |
| SIZE OF EXCAVATION: | | |
| ADDITIONAL COMMENTS: | | |


| GR | HERRON AVENUE SI ID EXCAVATION SUM | | |
|-------------------------|--|---|--|
| DATE: | 10/2/104 | | |
| GRID: | 108 | | |
| # OF DRUMS REMOVED: | 3 | 3 | |
| DEBRIS: | Misc. Matal Tires - 2 | | |
| DEPTH OF SAND: | 15' | | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | | |
| COORDINATES: | Northing Easting 4336885 711420 | | |
| SIZE OF EXCAVATION: | 10'x 15 'x 15' | | |
| ADDITIONAL COMMENTS: | | | |

| GRI | HERRON AVENUE SITE D EXCAVATION SUMMA | RY |
|-------------------------|---------------------------------------|----------------------------------|
| DATE: | 10/04/04 | |
| GRID: | 12-1 Test Trend | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Misc. Debris Tines - 1 | |
| DEPTH OF SAND: | 22' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid Excavated mater | ial |
| COORDINATES: | Northing H221 02 | Easting North |
| | 4336925 | 7/1425 - North 7/1435 - South |
| SIZE OF EXCAVATION: | 15 'x 20 'x 22 ' | |
| ADDITIONAL COMMENTS: | | |
| | | |

| GR | HERRON AVENUE SITE DEXCAVATION SUMMA | |
|-------------------------|--|-----------------------|
| DATE: | 10/05/04 | |
| GRID: | Test Trener # | 0-1 |
| # OF DRUMS REMOVED: | 98 | |
| DEBRIS: | Misc. Metal Tines-16 | |
| DEPTH OF SAND: | 15-22 | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | |
| COORDINATES: | Northing 4336895 | Easting 711415 711425 |
| SIZE OF EXCAVATION: | 20 x 35 x 22' | |
| ADDITIONAL COMMENTS: | | |

66. UI - '4 mort: horrangero JAM HTSICH '66 UI - '4 mort: horrangero JAM HTWOZ

'71-21 TA palo 3+402



| GR | HERRON AVENUE SITE | ARY |
|-------------------------|--|-------------------------|
| DATE: | 10/07/04 | |
| GRID: | test trener 11-2 | |
| # OF DRUMS REMOVED: | 20 | |
| DEBRIS: | misc. Debiis | |
| DEPTH OF SAND: | 15' | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | |
| COORDINATES: | Northing 4336915 43386915 | Easting 711 430 711 420 |
| SIZE OF EXCAVATION: | 15 × 25 × 15 | |
| ADDITIONAL COMMENTS: | | |

| GR | HERRON AVENUE SITE D EXCAVATION SUMMA | \RY | |
|-------------------------|---------------------------------------|----------------|--|
| DATE: | 10/6/04 | | |
| GRID: | test trener 11-1 | | |
| # OF DRUMS REMOVED: | O | | |
| DEBRIS: | MISC. MUTH 1 TIRES - O | | |
| DEPTH OF SAND: | 20' | | |
| PHOTOS: | Sidewall | | |
| | Bottom of grid | | |
| | Excavated material | | |
| COORDINATES: | Northing | <u>Easting</u> | |
| | 4336915 | 711430 Eas | |
| | 433615 | 711420 East | |
| SIZE OF EXCAVATION: | 15 x 30 x 20' | | |
| ADDITIONAL COMMENTS: | | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | | |
|--|--|----------------------------------|--|
| DATE: | 10/12/04 | | |
| GRID: | Test trenen 10-2 | | |
| # OF DRUMS REMOVED: | 33 | | |
| DEBRIS: | Misc Metal, Caste Tines-1 | MISC MEXAL, CASIE, REGAR TINES-1 | |
| DEPTH OF SAND: | 15- | | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | | |
| COORDINATES: | Northing | Easting | |
| SIZE OF EXCAVATION: | 15 x 30 x 15 | | |
| ADDITIONAL COMMENTS: | | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | | |
|--|---|---|--|
| DATE: | 8/ 6/104 | | |
| GRID: | 11A | | |
| # OF DRUMS REMOVED: | 2 | | |
| DEBRIS: | MISC. METAl/CONSTIN TINES = 5 | MISC. METAllCONSTRUCTION Debris Tines = 5 | |
| DEPTH OF SAND: | 14' | | |
| PHOTOS: | Sidewall | | |
| | Bottom of grid | | |
| | Excavated material | | |
| COORDINATES: | Northing 433 6920 433 6920 433 6915 4336915 | Easting 711+15 - NW 711+20 - NE 711+15 - SW 711+20 - SE | |
| SIZE OF EXCAVATION: | 15 × 15 × 16 ' | | |
| ADDITIONAL COMMENTS: | Hit concrete covered pipe AT 12' | | |
| | | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | | |
|--|---|--|--|
| DATE: | 8//0/04 | | |
| GRID: | 17C/24A | | |
| # OF DRUMS REMOVED: | 0 | 0 | |
| DEBRIS: | Concrete SMALL AMOUNT OF METAL TUbeing TIRES = 127 | | |
| DEPTH OF SAND: | | | |
| PHOTOS: | Sidewall | | |
| | Bottom of grid | | |
| | Excavated material | | |
| COORDINATES: | Northing 433 6900 433 6900 433 6890 433 6890 | Easting 7113910 - NW 7111400 - NE 7113910 - SW | |
| SIZE OF EXCAVATION: | 1 () | 711400 - SE | |
| ADDITIONAL COMMENTS: | | | |
| | | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | | |
|--|---|---|--|
| DATE: | 8//6/04 | | |
| GRID: | 17B | | |
| # OF DRUMS REMOVED: | 29 | | |
| DEBRIS: | CONSTRUCTION Debiis | Construction Debis Tines = 6 | |
| DEPTH OF SAND: | 16 | | |
| PHOTOS: | Sidewall | | |
| | Bottom of grid | | |
| | Excavated material | | |
| COORDINATES: | Northing 4336895 4336895 4336896 4336880 | Easting 711410 - NW 711415 - NE 711415 - SW 711415 - 1815 | |
| SIZE OF EXCAVATION: | 15 x 50 x 16 | | |
| ADDITIONAL COMMENTS: | Encountered main Storm water time @ 7 feet depts. tire | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|-------------------------------|------------------|
| DATE: | 8////04 | |
| GRID: | 25 A | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Sheet Metal Tines=1 | |
| DEPTH OF SAND: | 2' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| | Exodvated mater | |
| COORDINATES: | Northing | Easting |
| | 4336910 4336910 4336905 | 711395 711390 |
| | 4336910 | 711385 |
| | 43369.08 | 711390 |
| SIZE OF EXCAVATION: | 11 × 11 x 2'5" | |
| ADDITIONAL COMMENTS: | | |
| | | |

1.

| | | G. S. |
|-------------------------|---------------------------------------|---|
| GR | HERRON AVENUE SITE D EXCAVATION SUMMA | £ 3 |
| DATE: | 8//7/04 | |
| GRID: | H25B | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Slag, Misc MeTA | (|
| DEPTH OF SAND: | 2' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | <u>Northing</u> | <u>Easting</u> |
| | 4336910 - N | 711380-€ |
| SIZE OF EXCAVATION: | 4 x 6 x 6' | |
| ADDITIONAL COMMENTS: | | |
| , | | |

eger.

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|---|---|
| DATE: | 8/ <i>13</i> /04 | |
| GRID: | 27A | |
| # OF DRUMS REMOVED: | 5 | |
| DEBRIS: | CAR DOORS, Sheet Me Misc. Reban AND STEE! TIRES= 41 | TWI, CONSTRUCTION Debris |
| DEPTH OF SAND: | 22' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated material | |
| | Exocuted mater | |
| COORDINATES: | Northing 4336960 4336960 4336940 4336940 | Easting 711375-ND 711395-ND 711380-SW 711395-8E |
| SIZE OF EXCAVATION: | 53 x 45 x 22 | |
| ADDITIONAL COMMENTS: | | |
| | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|--|---|
| DATE: | 8/5 /04 | |
| GRID: | 20A | |
| # OF DRUMS REMOVED: | 0 | |
| DEBRIS: | Misc. CONSTRUCTION rebar) | sebiis (concrete, |
| DEPTH OF SAND: | 14 | |
| PHOTOS: | Sidewall Bottom of grid Excavated materi | ial |
| COORDINATES: | Northing 4336960 4336960 4336965 4336965 | Easting 711395 - NW 711400 - NE 711395 - SW 711400 - SE |
| SIZE OF EXCAVATION: | 16 × 16 × 14 | |
| ADDITIONAL COMMENTS: | | |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|--|---|
| DATE: | 8/ /04 | |
| GRID: | 20B | |
| # OF DRUMS REMOVED: | | |
| DEBRIS: | | |
| DEPTH OF SAND: | | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated material | |
| | | |
| COORDINATES: | Northing 433 69 60 433 69 55 433 69 55 | Easting 71141¢ - NW 711415 - NE 71141¢ - SW 711415 - SE |
| SIZE OF EXCAVATION: | | |
| ADDITIONAL COMMENTS: | | |

, ,

HERRON AVENUE SITE GRID EXCAVATION SUMMARY 8/6/04 DATE: 18A/11B GRID: **# OF DRUMS REMOVED:** 45 Pipe, Concrete, Rebar, slag **DEBRIS:** Tines = 7 17' **DEPTH OF SAND:** PHOTOS: Sidewall Bottom of grid **Excavated material Easting** COORDINATES: **Northing** 711410 - NW 4336915 711420 - NE 4336915 711410 - SW 433 6905 4336905 711420 -SE SIZE OF EXCAVATION: 30 ×30 × 17 **ADDITIONAL COMMENTS:** HiT concrete covering Pipe AT 12'

HERRON AVENUE SITE GRID EXCAVATION SUMMARY DATE: 8/9/04 18B/17A GRID: 58 # OF DRUMS REMOVED: Fill DIRT WITH WOOD AND METAL Debris **DEBRIS:** Tires = Co 16 DEPTH OF SAND: Sidewall PHOTOS: Bottom of grid **Excavated material Northing** Easting COORDINATES: 711410 4336905 711415 4336905 711410 4336895 4336898 711415 25 x 40 x 110 SIZE OF EXCAVATION: 2 drums with labels remard - Delta Chennical Co. - Another Fremost Product ADDITIONAL **COMMENTS:**

~~ >4

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | | |
|--|--|---|--|
| DATE: | 8/ 5 /04 | | |
| GRID: | 19B | 19B | |
| # OF DRUMS REMOVED: | 2 | | |
| DEBRIS: | SMALL AMOUNT OF M TIRES = 106 | SMALL AMOUNT OF METAL TIRES = 106 | |
| DEPTH OF SAND: | 15 ' | | |
| PHOTOS: | Sidewall Bottom of grid Excavated material | | |
| COORDINATES: | Northing 433 6935 433 6935 433 6925 433 6925 | Easting 711410 - NW 711415 - NE 711410 - BW 711415 - SE | |
| SIZE OF EXCAVATION: | ZO'XZO'X 15' | | |
| ADDITIONAL COMMENTS: | Lateral cracked @ 9 feet | | |

| GR | HERRON AVENUE SITE ID EXCAVATION SUMMA | ARY |
|---------------------|--|---|
| DATE: | 8/4/04 | |
| GRID: | 19A | |
| # OF DRUMS REMOVED: | 29 | |
| DEBRIS: | misc. metal + beb. | ris Tires = 13 |
| DEPTH OF SAND: | 18' | |
| PHOTOS: | Sidewall | |
| 1 | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | Northing 43369 40 43369 40 43369 30 43369 30 | Easting 71(400 - NW 71(405 - NE 71(400 - SW 71(405 - SE |
| SIZE OF EXCAVATION: | 30'x30'x18' | |

| GR | HERRON AVENUE SITE ID EXCAVATION SUMMA | |
|----------------------|--|----------------|
| DATE: | 8/12/04 | |
| GRID: | 268 | |
| # OF DRUMS REMOVED: | ø | |
| DEBRIS: | 1 tre | |
| DEPTH OF SAND: | Sand up to 10 f | Pat |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | rial |
| COORDINATES: | Northing | <u>Easting</u> |
| | 4336131.0 | 7113753 |
| | 7,700,000 | VVID 13 J |
| SIZE OF EXCAVATION: | 4'26' | |
| ADDITIONAL COMMENTS: | Sand from Jackval | concernters |
| | lots of garbage | /grass, ex |

10 mg 18 mg

| GR | HERRON AVENUE SITE | ARY |
|----------------------|--|-------------------------------------|
| DATE: | 8///104 | |
| GRID: | 26A | |
| # OF DRUMS REMOVED: | 4 | |
| DEBRIS: | 2 CAR HOODS, Reban, SH- | eet MeTAI, STEEL CaSIF |
| DEPTH OF SAND: | 18-27 | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | Northing 43369 40 43369 40 43364 20 43369 20 | Easting 711325 711395 711395 711395 |
| SIZE OF EXCAVATION: | 37 x69×17 | |
| ADDITIONAL COMMENTS: | Grid begins AT 27 | T'AND GOES DOWN TO |

| HERRON AVENUE SITE GRID EXCAVATION SUMMARY | | |
|--|--------------------|---------|
| DATE: | 8/14/04 | |
| GRID: | 284 - Test-trev | ch |
| # OF DRUMS REMOVED: | 2 | |
| DEBRIS: | RebAR, MISC. METAL | |
| DEPTH OF SAND: | 12' | |
| PHOTOS: | Sidewall | |
| | Bottom of grid | |
| | Excavated mater | ial |
| COORDINATES: | Northing | Easting |
| | | |
| SIZE OF EXCAVATION: | 15×50×12' Tre | veh |
| ADDITIONAL COMMENTS: | | |